

## SERVICE RESET FOR VOLVO

Dear customer,

During our verification tests at some garages to verify the correct functioning of auto diagnosis procedures, we have found out that in some Volvo cars like V70 and S60, the reset service procedure didn't erase the interval service. Brain bee's database procedures are correct, but these cars follow a different procedure, e.g. Volvo S60 D5 registration year 2002.

Volvo has inserted a new manual procedure for the reset service, different from the first procedures.

For this reason, with CD 65 we have scheduled the insertion of a new manual procedure for the Volvo V70 and S60 models.

We'll insert the new procedure in the "MANUAL INSPECTION" system.

However, we prefer to send you the new procedure in advance, so that you'll be able to help your clients until the release of CD 65. You can inform them that the procedure will be inserted on Brain Bee's database from the next version.

### **SERVICE RESET PROCEDURE FOR VOLVO V70-S60:**

#### TYPE 1:

- with ignition off, press and keep pressed the button that selects trip/total kilometres
- turn ignition on
- at the second blink of the service light (or the trip odometer indicator), release the button
- turn ignition off



# TECH news

On some vehicles, the above procedure does not work, so it's necessary to proceed as follows:

## TYPE 2:

- with ignition off, press and keep pressed the button that selects trip/total kilometres
- turn the ignition key on the first position (only some part of the dashboard will turn on)
- after some seconds, an acoustic signal will be heard, at this point release the button in less than 4 seconds
- wait for 10 seconds and turn ignition key off

We hope you may find this information useful, and we invite you to contact us in case you may have any questions.

**After Sales Department's Technical Staff**



Azienda certificata  
con sistema di qualità ISO 9001

